

## Bar Floor

**Project:** Bar Floor

**Category:** Commercial Flooring

**Completion**

**Date:** September 2003

**System:** Pedestrian Access

**Product::** TUFF STUFF

## Job Description

This bar floor was badly damaged, slippery and did not have correct fall to the drains.

The floor was re-levelled prior to installing Rhino Linings TUFF STUFF using the Pedestrian Access Flooring System. The entire job took two days and the bar was put back into service 3 hours after completion.

The Rhino Linings Flooring System has provided a seamless, durable, slip resistant surface meeting Health and OH&S requirements.

**Before...**



**After...**

