

Mezzanine Floor

Project: Factory Mezzanine Floor

Category: Commercial Flooring

Completion

Date: March 2005

System: Pedestrian Access

Product: Duraspray



Before...

Job Description

This factory had a serious safety issue with employees slipping on the existing flooring due to the floor becoming coated with a fine layer of chocolate dust during shifts. Management chose Rhino Linings Pedestrian Access Flooring System to resolve the OH& S issue.

The steel mezzanine floor and a heavy forklift area were sprayed with Duraspray and an aggregate topcoat providing a seamless, durable lining with slip resistant properties.



After...

